

## ZZZZ396 – Checking of the adjustment of the quadratic levels sets for the cracks segments

---

### Summary:

This test makes it possible to validate the good progress of the adjustment of the quadratic levels sets in the two-dimensional case of a crack segment (DEFI\_FISS\_XFEM / DEFI\_FISS / FORM\_FISS=' SEGMENT ').

This documentation is voluntarily brief.